

# WEST Search History

Hide Items Restore Clear Cancel

DATE: Monday, December 27, 2004

09752879

Hide?	Set Name	Query	Hit Count
		<i>DB=PGPB,USPT,EPAB,JPAB,DWPI,TDBD; PLUR=YES; OP=ADJ</i>	
<input type="checkbox"/>	L24	('4253183')!.ABPN1,NRPN,PN,TBAN,WKU.	2
<input type="checkbox"/>	L23	('20020040456')!.ABPN1,NRPN,PN,TBAN,WKU.	2
<input type="checkbox"/>	L22	control\$4 with snap\$4shot with shift\$3 same (clock\$3 or timing or sync or synchron\$7 or sinchron\$7) and l21	4
<input type="checkbox"/>	L21	snap\$4shot with shift\$3 same (clock\$3 or timing or sync or synchron\$7 or sinchron\$7)	43
<input type="checkbox"/>	L20	L19 and @pd > 20040127	0
<input type="checkbox"/>	L19	('6665816')!.ABPN1,NRPN,PN,TBAN,WKU.	2
		<i>DB=USPT,PGPB,JPAB,EPAB,DWPI,TDBD; PLUR=YES; OP=ADJ</i>	
<input type="checkbox"/>	L18	((('5812830'  '5951696'  '5701308') [ABPN1,NRPN,PN,TBAN,WKU])) and @pd > 20031015	0
<input type="checkbox"/>	L17	(L15 and boundary with scan\$4 and (global or system or core or main)near2 (clock\$3 or timing or sync or synchron\$7 or sinchron\$7) and intern\$4 near(bus or line)with (test\$3 or debug\$4) and register with (instruct\$3 or command\$3) and (skew\$3 or de\$1skew\$3)) and @pd > 20031015	0
<input type="checkbox"/>	L16	(L14 and boundary with scan\$4 and (global or system or core or main)near2 (clock\$3 or timing or sync or synchron\$7 or sinchron\$7) and intern\$4 near(bus or line) and register with (instruct\$3 or command\$3) and (skew\$3 or de\$1skew\$3) and (test\$3 or debug\$4)) and @pd > 20031015	9
<input type="checkbox"/>	L15	(L13 and boundary with scan\$4 and (global or system or core or main)near2 (clock\$3 or timing or sync or synchron\$7 or sinchron\$7) and (bus or line) and register with (instruct\$3 or command\$3) and (skew\$3 or de\$1skew\$3) and (test\$3 or debug\$4)) and @pd > 20031015	0
<input type="checkbox"/>	L14	(L12 and boundary with scan\$4 and (global or system or core or main)near2 (clock\$3 or timing or sync or synchron\$7 or sinchron\$7) and (bus or line) and register with (instruct\$3 or command\$3) and (skew\$3 or de\$1skew\$3)) and @pd > 20031015	16
<input type="checkbox"/>	L13	(L11 and boundary with scan\$4 and (global or system or core or main)near2 (clock\$3 or timing or sync or synchron\$7 or sinchron\$7) and (bus or line) and register with (instruct\$3 or command\$3)) and @pd > 20031015	0
<input type="checkbox"/>	L12	(L10 and boundary with scan\$4 and (global or system or core or main)near2 (clock\$3 or timing or sync or synchron\$7 or sinchron\$7)) and @pd > 20031015	139
<input type="checkbox"/>	L11	(L9 and boundary with scan\$4) and @pd > 20031015	0
<input type="checkbox"/>	L10	(ieee\$1149\$2) and @pd > 20031015	31766
		<i>DB=PGPB,USPT,USOC,EPAB,JPAB,DWPI,TDBD; PLUR=YES; OP=ADJ</i>	
<input type="checkbox"/>	L9	('6014752')!.PN.	2

<input type="checkbox"/>	L8	L4 and 'tap' with control\$4 with '1149' with (state or machine) and sync	0
<input type="checkbox"/>	L7	L4 and 'tap' with control\$4 with '1149' with (state or machine) and skew\$3	0
<input type="checkbox"/>	L6	L4 and 'tap' with control\$4 with '1149' with (state or machine) and de\$2skew\$3	0
<input type="checkbox"/>	L5	L4 and 'tap' with control\$4 with '1149' with (state or machine) same de\$2skew\$3	0
<input type="checkbox"/>	L4	L1 and 'tap' with control\$4 with '1149' with (state or machine)	21
<input type="checkbox"/>	L3	L1 and 'tap' with control\$4 with '1149' and finite near3 (state or machine)	3
<input type="checkbox"/>	L2	L1 and 'tap' with control\$4 with '1149' same finite near3 (state or machine)	0
<input type="checkbox"/>	L1	'tap' with control\$4 with '1149'	28

END OF SEARCH HISTORY